## 2013-2014 Year Expenses Repairs on Motors, Pumps, and Blowers

## **Laredo Machine Shop:**

2. 3. 4. 5. 6. 7. 8. 9.	Fabricate Flanges for Second River Intake Pump	\$798.00 \$2,498.00 \$880.00 \$2,378.00 \$1,782.00 \$2,278.00 \$1,000.00 \$3,900.00 \$490.00 \$500.00	801-3001-6402 801-3001-6402 801-3001-6402 801-3001-6402 801-3001-6205 801-3001-6402 801-3004-6402 801-3004-6402 801-3004-6402	
Kruge	<u>r:</u>			
2. 3. <u>Odess</u>	Recirculation Pump for Water Plant needed Recirculation Pump Repair Kits (2) for damage pumps Recirculation Pump Repair Kits (2) for damage pumps Rea Pumps & Equipment: Purchased a new Pump for River U Series Pump #U6A6OS-B/F Overhaul of Pump at Wastewater Plant T-Series #T4A3S-B	\$7,595.40 \$2,579.16 \$2,989.50 \$9,265.78 \$2,496.90	801-3001-6402 801-3001-6402 801-3004-6402 801-3001-6402 801-3004-6402	
Moody Bros Inc:				
1. 2.	Purchasing of an Encore 700Pump Alum Pump for Water Plant Purchasing of Polyflex Belts for Alum Pumps at Water Plant	\$4,074.30 \$626.60	801-3001-6402 801-3001-6205	
Delta House Electric:				
1. 2. 3. 4. 5.	Rewind 10hp Centrifugal Pump for RO at Colorado Acres Repaired 10hp Straight Discharge Pump at Colorado Acres	\$4,226.14 \$1,724.97 \$3,965.44 \$5,994.60 \$2,059.52	801-3001-6402 801-3002-6402 801-3002-6402 801-3002-6402 801-3002-6402	
Velocity Dynamics				
1.	Repair Kits for the Polymer Pumps used at the Water Plant	\$2,798.17	801-3001-6402	
Ron Perrin Water Technologies				
	Annual Tank Inspection for the Rio Bravo Water Plant Annual Tank Inspection for the Colorado Acres Water Plant	\$2,183.00 \$1,296.00	801-3001-6402 801-3002-6402	

## **HD Supply Waterworks**

1. 2. 3. 4. 5.	Meters, Meter Connections, and Angle Valves for Distribution Equipment needed for New Water Taps and Replacements Locks, Keys, and Caps needed in the Closing of Water Services Equipment used to Drain and Clean Clarifiers at the Water Plant Barrel Locks and Dust Caps to Close Water Services	\$1,315.20 \$3,008.16 \$311.60 \$1,647.60 \$286.70	801-3001-6407 801-3002-6402 801-3002-6205 801-3002-6402 801-3002-6407	
Bohls Equipment and Bearing				
1. 2. 3. 4. 5.	6" Discharge for River Intake Mobile Pump V Belts needed to repair Mobile River Intake Pump	\$462.73 \$2,100.00 \$295.86 \$134.90 \$284.42	801-3004-6205 801-3001-6402 801-3001-6402 801-3004-6402	
Lowe's Home Center				
1.	25btu Window Unit for the Electrical Room at the Sewer Plant	\$531.05	801-3004-6402	
ACT Pipe & Supply				
1. 2. 3.	34" Concrete Ring for the Sewer Collection System Repairs Materials used for Water Main Leak by Espejo Molina Rd. Materials used to repair Water Leak by River Valley Rd.	\$654.57 \$2,369.48 \$663.65	801-3004-6407 801-3002-6205 801-3001-6407	

TOTAL: \$84,445.40

NOTE: This list does not include any tools, chemicals, building repairs, or vehicles.