

LITTLETON CLAIMS SERVICE LLC  
923 CHALAN STREET  
LAREDO, TX 78045  
PHONE: 956-740-0883 FAX: 956-726-4742

\*\*\* PRELIMINARY ESTIMATE \*\*\*

04/17/2024 07:50 AM

**Owner**

**Owner:** SERGIO CHAIRES

**Control Information**

**Claim # :** 24911297  
**Loss Date/Time:** 03/14/2024 07:48 AM  
**File # :** LG137991

**Insured Policy # :** NA  
**Loss Type:** Liability  
**Accounting # :**

**Ins. Company:** The Littleton Group  
**Company Contact:** TRISTAR RISK MANAGEMENT  
**Address:** P.O. Box 440618  
**City State Zip:** Laredo, TX 78044  
**Email:** Avalencia@Littletongroup.com

**Work/Day:** (956)726-6150  
**FAX:**

**Insured:** WEBB COUNTY

**Claimant:** SERGIO CHAIRES

**Claim Rep:** DAVID GUERRERO

**Inspection**

**Inspection Date:** 04/11/2024 07:48 AM  
**Inspection Location:** 2611 COMAL LOOP  
**City State Zip:** Laredo, TX 78046

**Inspection Type:** Field  
**Contact:**  
**FAX:**

**Appraiser Name:** Armando Valencia  
**Address:** P.O. Box 440618  
**City State Zip:** Laredo, TX 78044  
**Email:** Avalencia@Littletongroup.com

**Appraiser License #2 :**  
**Work/Day:** (956)726-6150  
**Home/Evening:** (956)740-0883  
**FAX:**

**Repairer**

**Target Complete Date/Time:**

**Days To Repair:** 7\*

**Remarks**

This is not an authorization to repair.  
Only the registered owner can provide authorization to begin repairs.  
No supplements will be authorized without prior approval.  
Additional damages may be noted after disassembly

**Vehicle**

**OEM Part Price Quote ID:** \*\*\*\*

2017 Chevrolet Impala 1LT 4 DR Sedan  
 4cyl Gasoline 2.5 DOHC  
 6-Speed Automatic

**Lic.Plate:** PWX9056  
**Lic Expire:**  
**Veh Insp# :**  
**Condition:**  
**Ext. Color:** BLACK  
**Ext. Refinish:** Two-Stage

**Lic State:** TX  
**VIN:** 2G1105SA5H9175152  
**Mileage Type:** Actual  
**Code:** U4183B  
**Int. Color:**  
**Int. Refinish:**

**Options**

1st Row LCD Monitor(s)	2nd Row Head Airbags	AM/FM Stereo
Air Conditioning	Aluminum/Alloy Wheels	Anti-Lock Brakes
Auto Headlamp Control	Auxiliary Audio Input	Black Grille
Bucket Seats	Center Console	Compact Spare Tire
Cruise Control	Daytime Running Lights	Digital Clock
Driver Information Sys	Dual Airbags	Dual Zone Auto A/C
Electric Steering	Electronic Compass	Emergency S.O.S. System
Ext Mirror Turn Signals	Floor Mats	Halogen Headlights
Head Airbags	Heated Power Mirrors	High Definition Radio
IPOD Control	Illuminated Visor Mirror	In-Vehicle WiFi
Intermittent Wipers	Keyless Entry System	Knee Air Bags
Leather Shift Knob	Leather Steering Wheel	Lighted Entry System
MP3 Decoder	OnStar System	Overhead Console
Power Brakes	Power Door Locks	Power Drivers Seat
Power Windows	Pwr Accessory Outlet(s)	Pwr Driver Lumbar Supp
Rear Side Airbags	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	Side Mirror Lighting	SiriusXM Satellite Radio
Split Folding Rear Seat	Stability Cntrl Suspensn	Strg Wheel Radio Control
Tachometer	Theft Deterrent System	Tilt & Telescopic Steer
Tinted Glass	Tire Pressure Monitor	Touch Screen Display
Traction Control System	Trip Computer	USB Audio Input(s)
Vehicle Tracking Service	Velour/Cloth Seats	Wireless Audio Streaming
Wireless Phone Connect		

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R	
<b>Front Bumper</b>											
1	EU	6	46	Bumper Assembly,Front	Replace Recycled	\$350.00*			3.3	SM	
2	L	6	13	Cover,Front Bumper	Refinish				4.4	RF	
3	EP	31		Cushion,Front Bumper LT	Replace PXN	\$8.57				SM	
4	EP	32		Cushion,Front Bumper RT	Replace PXN	\$8.57				SM	
5	EP	18		Reinf,Frt Bumper Upr LT	Replace PXN	\$16.00			INC	SM	
6	E	1140		Ret,Frt Bumper Cover	11612035 GM Part	\$27.76				SM	
				Quantity of 4 @ \$6.94 each							
7	EP	24		Sensor,Temperature	Replace PXN	\$8.49			0.1	ME	
8	EP	15		Defl,Front Bumper Lwr	Replace PXN	\$14.73			0.2	SM	
9	EP	16		Defl,Front Bumper Lwr LT	Replace PXN	\$11.93			0.1	SM	
10	EP	17		Defl,Front Bumper Lwr RT	Replace PXN	\$11.93			0.1	SM	
11	RI	26		Filler,Front Bumper LT	R & I Assembly				0.2	SM	
12	RI	27		Filler,Front Bumper RT	R & I Assembly				0.2	SM	
13	EP	7		Absorber,Front Bumper	Replace PXN	\$112.00			0.2	SM	
<b>Front End Panel And Lamps</b>											
14	EP	28		Grille Assembly	Replace PXN	\$334.00			0.3	SM	

15	EP	41	Headlamp Assy,Halogen LT	Replace PXN	\$636.00	INC	SM
16	N	973	Headlamps Aim	Additional Labor		0.4	SM

**Front Body And Windshield**

17	I	83	Panel,Hood	Repair		3.0*	SM
18	L	83	Panel,Hood	Refinish		3.6	RF
19	I	103	Fender,Front LT	Repair		1.0*	SM
20	L	103	Fender,Front LT	Refinish		2.2	RF

**Front Body Interior Sheetmetal**

21	EP	113	Skirt,Inner Fender LT	Replace PXN	\$55.00	0.3	SM
----	----	-----	-----------------------	-------------	---------	-----	----

**Manual Entries**

22	SB	M03	Flex Additive	Sublet Repair	\$7.50*		RF
23	SB	M17	Cover Car Exterior	Sublet Repair	\$7.50*	0.3*	RF
24	SB	M60	Hazardous Waste Removal	Sublet Repair	\$7.50*		SM
<b>24 Items</b>							

**MC Message**

13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE
46	PRINTABLE ALTERNATE PARTS COMPARE

**Estimate Total & Entries**

<b>OEM Parts</b>		\$27.76	
<b>Other Parts</b>		\$1,567.22	
<b>Paint &amp; Materials</b>	10.5 Hours @ \$35.00	\$367.50	
<b>Parts &amp; Material Total</b>			\$1,962.48
<b>Tax on Parts &amp; Material</b>	@ 8.250%		\$161.90

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$45.00	4.9	4.4	9.3	\$418.50
Mech/Elec (ME)	\$45.00	0.1		0.1	\$4.50
Frame (FR)	\$45.00				
Refinish (RF)	\$45.00	10.2	0.3	10.5	\$472.50

<b>Labor Total</b>			19.9 Hours	\$895.50
<b>Tax on Labor</b>	@ 8.250%			\$73.88
<b>Sublet Repairs</b>				\$22.50
<b>Gross Total</b>				<b>\$3,116.26</b>
<b>Net Total</b>				<b>\$3,116.26</b>

Alternate Parts Y/12/11/00/01/01 Cumulative 12/11/00/01/01 Zip Code: 78045 Geo 78045  
 OEM Part Prices DT 04/17/2024 07:51 AM EstimateID 1209844719182422016 QuoteID \*\*\*\*  
 SPPL Yes Zip Code: 78040 Default  
 Rate Name Default

Audatex Estimating 8.2.444 ES 04/17/2024 07:58 AM REL 8.2.444 DT 04/01/2024 DB 04/15/2024  
 State Disclosure: Not Selected  
 © 2024 Audatex North America, LLC.

**2.2 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.**

THIS IS NOT AN AUTHORIZATION TO REPAIR OR AN ACCEPTANCE OF LIABILITY. PLEASE  
PRESENT A COPY OF THIS ESTIMATE TO THE REPAIR SHOP OF YOUR CHOICE.  
NO SUPPLEMENTS HONORED WITHOUT PRIOR INSPECTION AND APPROVAL OF THE APPRAISER.

### Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2024 Audatex North America, LLC.  
AUDATEX is a trademark owned by Audatex  
North America, LLC. All rights reserved.