



**Webb County
Purchasing Department
Bid Tabulation**

**Bid : 2017-17
Maintenance, Inpection, & Repair of
Webb County Fire Extinguishers**

Contract Term:

October 1, 2016 to September 30, 2017

If extended expires: September 30, 2018

FireXT Corporation
c/o Ramiro Coutino |
11127 Carrizo Dr.
Laredo, TX 78045
956-693-0301 |
ramiro@firextcorporation.com

Profire Protection, Inc.
c/o Bernardo De Leon
455 Lantana
Corpus Christi, TX 78408
361-299-5100
profire01@aol.com

SimplexGrinnell LP
c/o A. Melton
1070 Arion Circle
Suite 102
San Antonio, TX 78216
210-402-6311
almelton@simplexgrinnell.com

Secondary

Primary

QTY	ITEM DESCRIPTION			Unit Price	Ext. Price	UNIT PRICE	TOTAL PRICE
Fire Extinguishers							
Item I: New Fire Extinguishers with metal valve heads accepted only							
25	2 1/2 lb ABC, BC, Dry Chemical	\$ 35.00	\$ 875.00	\$ 48.58	\$ 1,214.50	\$ 32.00	\$ 800.00
25	5 lb ABC, BC, Dry Chemical	\$ 55.00	\$ 1,375.00	\$ 62.50	\$ 1,562.50	\$ 55.00	\$ 1,375.00
25	10 lb ABC, BC, Dry Chemical	\$ 75.00	\$ 1,875.00	\$ 113.58	\$ 2,839.50	\$ 65.00	\$ 1,625.00
25	20 lb ABC, BC, Dry Chemical	\$ 155.00	\$ 3,875.00	\$ 208.58	\$ 5,214.50	\$ 125.00	\$ 3,125.00
25	5 lb Halon (replacement)	\$ 240.00	\$ 6,000.00	\$ 225.38	\$ 0.00	\$ 175.00	\$ 4,375.00
25	10 lb Halon (replacement)	\$ 400.00	9lb \$ 10,000.00	\$ 457.69	\$ 0.00	\$ 350.00	\$ 8,750.00
25	20 lb Halon (replacement)	\$ 700.00	17lb \$ 17,500.00	\$ 754.62	\$ 0.00	\$ -	
25	CO 5 lb	\$ 147.00	\$ 3,675.00	\$ 216.00	\$ 5,400.00	\$ 145.00	\$ 3,625.00
25	CO 10 lb	\$ 230.00	\$ 5,750.00	\$ 315.75	\$ 7,893.75	\$ 185.00	\$ 4,625.00
25	CO 15 lb	\$ 270.00	\$ 6,750.00	\$ 362.25	\$ 9,056.25	\$ 221.00	\$ 5,525.00
25	CO 20 lb	\$ 315.00	\$ 7,875.00	\$ 407.15	\$ 10,178.75	\$ 300.00	\$ 7,500.00
Total Section I			\$ 65,550.00		\$ 43,359.75		\$ 41,325.00
Item II: Vehicle Brackets for Trucks, Semi or Tractors							
50	2 1/2 lb (installation included)	\$ 25.00	\$ 1,250.00	\$ 29.74	\$ 1,487.00	\$ 15.00	\$ 750.00
50	5 lb (installation included)	\$ 45.00	\$ 2,250.00	\$ 30.78	\$ 1,539.00	\$ 15.00	\$ 750.00
50	10 lb (installation included)	\$ 52.00	\$ 2,600.00	\$ 69.86	\$ 3,493.00	\$ 42.00	\$ 2,100.00
50	20 lb (installation included)	\$ 60.00	\$ 3,000.00	\$ 80.96	\$ 4,048.00	\$ 50.00	\$ 2,500.00
Total Section II			\$ 9,100.00		\$ 10,567.00		\$ 6,100.00
Item III:							
(A.) Type ABC							
#1	2 1/2 lbs						
	recharge fee	\$ 10.00		\$ 7.50		\$ 28.00	
	replacement fee	\$ 35.00		\$ 48.58		\$ 32.00	
	inspection fee	\$ 7.00		\$ 5.00		\$ 3.00	
	hydro test (12 yrs)						
	6-year maintenance	\$ 10.00		\$ 7.50		\$ 31.00	
(A.) Type ABC							
#2	5 lbs						
	recharge fee	\$ 18.00		\$ 12.75		\$ 32.00	
	replacement fee	\$ 55.00		\$ 62.50		\$ 55.00	
	inspection fee	\$ 7.00		\$ 5.00		\$ 3.00	
	hydro test (12 yrs)						
	6-year maintenance	\$ 18.00		\$ 12.75		\$ 36.00	



**Webb County
Purchasing Department
Bid Tabulation**

**Bid : 2017-17
Maintenance, Inpection, & Repair of
Webb County Fire Extinguishers**

Contract Term:

October 1, 2016 to September 30, 2017

If extended expires: September 30, 2018

FireXT Corporation
c/o Ramiro Coutino |
11127 Carrizo Dr.
Laredo, TX 78045
956-693-0301 |
ramiro@firextcorporation.com

Profire Protection, Inc.
c/o Bernardo De Leon
455 Lantana
Corpus Christi, TX 78408
361-299-5100
profire01@aol.com

SimplexGrinnell LP
c/o A. Melton
1070 Arion Circle
Suite 102
San Antonio, TX 78216
210-402-6311
almelton@simplexgrinnell.com

Secondary

Primary

QTY	ITEM DESCRIPTION			Unit Price	Ext. Price	UNIT PRICE	TOTAL PRICE
	(A.) Type ABC						
	#3 10 lbs						
	recharge fee	\$ 25.00		\$ 17.00		\$ 40.00	
	replacement fee	\$ 75.00		\$ 113.58		\$ 65.00	
	inspection fee	\$ 7.00		\$ 5.00		\$ 3.00	
	hydro test (12 yrs)						
	6-year maintenance	\$ 25.00		\$ 17.00		\$ 42.00	
	(B.) C-02						
	#4 5 lbs						
	recharge fee	\$ 40.00		\$ 16.50	per lb	\$ 45.00	
	replacement fee	\$ 130.00		\$ 216.00		\$ 145.00	
	inspection fee	\$ 7.00		\$ 8.50		\$ 3.00	
	hydro test (5 yrs)						
	6-year maintenance	n/a		n/a		n/a	
	(B.) C-02						
	#5 10 lbs						
	recharge fee	\$ 70.00		\$ 16.50	per lb	\$ 75.00	
	replacement fee	\$ 185.00		\$ 315.75		\$ 185.00	
	inspection fee	\$ 7.00		\$ 8.50		\$ 3.00	
	hydro test (5 yrs)						
	6-year maintenance	n/a		n/a		n/a	
	(C.) Water Pressure						
	#6 2 1/2 lbs						
	recharge fee	\$ 35.00		\$ 12.00		\$ 30.00	
	replacement fee	\$ 125.00		\$ 136.95		\$ 115.00	
	inspection fee	\$ 7.00		\$ 5.00		\$ 3.00	
	hydro test (5 yrs)			n/a		n/a	
	(D.) FE-36						
	#7 10 lbs					\$ 175.00	
	recharge fee	no bid		\$ 19.00		n/a	
	inspection fee	\$ 7.00		\$ 5.00		\$ 3.00	
	hydro test (12 yrs)						
	(E.) 5# ABC Repairs / Replacement						
	#8 Valve Stem Replacement Fee	\$ 9.00		\$ 12.50		0	
	#9 Pull Pin Replacement Fee	\$ 1.00		\$ 2.50		0	
	#10 O-Ring Replacement Fee	\$ 1.00		\$ 2.50		0	
	#11 Gauge Replacement Fee	\$ 15.00		\$ 7.95	free	0	
	#12 Handle Replacement Fee	\$ 15.00		\$ 6.00	free	0	
	#13 Hose Replacement Fee	\$ 15.00		\$ 18.75		0	
	Total Section III	961.00		\$ 1,124.06		\$ 1,152.00	
	Additional Charges:						
	Service Call			\$ 46.75			
	<i>(For each inspection, maintenance, repair trip made for each location)</i>						
	<i>24 hour notice is required for any rescheduling if notice is not given a rescheduling fee will be charged</i>			\$184.25			
	<i>Fire extinguishers should be made accessible prior to the arrival of a technicians</i>						
	Grand Total for Fire Extinguishers (Item II, III, IV)	\$ 75,611.00		\$ 55,050.81		\$ 48,577.00	