

Laredo Machine Shop

PO Box 440641
 Laredo, TX
 78044-0641

Estimate

Date	Estimate #
2/23/2016	693

Name / Address
Webb County Water Utility 1110 Washington suite 101 Laredo, Texas 78041

Description	Qty	Cost	Project
			Total
Cost to ordered a new Denver Gardner blower with all the accessions recommended by Garden Denver Distributor.		8,975.00	8,975.00
Parts that need to be replace: Pulley for motor Bushing pulley for motor Pulley for Blower Bushing for Blower Power Belts Air Filter Wire clement Lube / 5Gallons Will remove damage parts and install new ones. Will Machine grind and polish area prior to install new parts. Order a new DuroFlow Gardner Denver Blower. Remove damage blowers and install new one. Prior to install new blower on original skid will machine grind surface and clean metal frames. Service Charges to Ship Blower and parts.		21,980.00	21,980.00
*****There will be no warranty if blower fails to meet requirements due to lack of Maintenance.***** ***** Please note that pipes air vents were not checked by Technicians***** Technicians from Garden Denver are recommending parts as per customer request. 6-8Week estimated time of delivery Mr. Jesus Benavies		1,575.00	1,575.00
		Subtotal	\$32,530.00
		Sales Tax (8.25%)	\$0.00
		Total	\$32,530.00