



Cervantes Truck Center, Inc.  
 5502 State Hwy 359  
 Laredo, TX 78043  
 PH (956) 723-0860

# Estimate

Date	Estimate #
8/18/2022	2022-0905

Name / Address
Webb County Attn: Business Office 1110 Washington Street, Ste #203 Laredo, Tx 78040

			Project
Description	Qty	Rate	Total
Computer Diagnostic Engine: Cummins S/N: 57924439 Detected: Fault Codes: 1993: Aftertreatment 1 Diesel Particulate Filter Missing 1883: Aftertreatment 1 Diesel Particulate Filter Differential Pressure 2634: VGT Actuator Controller 2636: VGT Actuator Driver Circuit 2963: Engine Coolant Temperature Reset Codes & Updated Software	1	225.00	225.00
Diesel Truck Service - Turbo Drain Coolant Remove All Necessary Components To Remove VGT From Turbo; Check Turbo Lever; Detected Is Stuck (BAD TURBO); Remove & Replace Turbo & VGT Calibrate VGT To Turbo; Reinstall All Components	1	1,200.00	1,200.00
Diesel Truck Service - EGR Valve Run Test On EGR Valve ( Test Failed) Remove EGR Valve; Detected It Has Too Much Carbon With Coolant In The EGR Housing; Remove All Necessary Components To Remove EGR Housing Clean As Necessary; Reinstall EGR Housing, Install New EGR Valve Reinstall All Components	1	675.00	675.00
Thank you for your business.		<b>Subtotal</b>	
		<b>Sales Tax (8.25%)</b>	
		<b>Total</b>	

Phone #
9567230860

E-mail
CervantesTruckCenter@yahoo.com



Cervantes Truck Center, Inc.  
 5502 State Hwy 359  
 Laredo, TX 78043  
 PH (956) 723-0860

# Estimate

Date	Estimate #
8/18/2022	2022-0905

Name / Address
Webb County Attn: Business Office 1110 Washington Street, Ste #203 Laredo, Tx 78040

			Project
Description	Qty	Rate	Total
Diesel Truck Service - EGR Cooler EGR Cooler Leaking Coolant; Detected Bad EGR Cooler; Remove All Necessary Components To Remove & Replace EGR Cooler; Reinstall All Components; Add New Coolant	1	1,200.00	1,200.00
Diesel Truck Service - Transfer Case Lift Rear End; Run Truck; Detected Knocking Sound Coming From Transfer Case; Remove Driveshaft & All Necessary Components To Remove Transfer Case (See Labor Below) Reinstall Transfer Case & All Components Add Gear Oil	1	780.00	780.00
Diesel Truck Service - Transfer Case Service Drain Fluid; Disassemble Complete Transfer Case; Detected Bad Gear & Ring; Replace Parts Mention; Re-Assemble Transfer Case & Adjust Gear As Necessary	1	1,500.00	1,500.00
Diesel Truck Service - Driveshaft #1 Run Driveshaft On Lathe Detected Weld Yoke It's Running Crooked Remove Weld & Straighten As Necessary Re-Weld Yoke	1	225.00	225.00
Industrial Machine Shop Services - Driveshaft #1 Replace Spline Plug & Re-Weld	1	225.00	225.00
Thank you for your business.		<b>Subtotal</b>	
		<b>Sales Tax (8.25%)</b>	
		<b>Total</b>	

Phone #
9567230860

E-mail
CervantesTruckCenter@yahoo.com



Cervantes Truck Center, Inc.  
 5502 State Hwy 359  
 Laredo, TX 78043  
 PH (956) 723-0860

# Estimate

Date	Estimate #
8/18/2022	2022-0905

Name / Address
Webb County Attn: Business Office 1110 Washington Street, Ste #203 Laredo, Tx 78040

			Project
Description	Qty	Rate	Total
Industrial Machine Shop Services - Driveshaft #1 Replace U-Joint From Driveshaft	1	75.00	75.00
Diesel Truck Service - Driveshaft #2 Run Driveshaft On Lathe Detected Good Driveshaft	1	75.00	75.00
Industrial Machine Shop Services - Driveshaft #2 Replace 2 U-Joints From Driveshaft	2	75.00	150.00
Industrial Machine Shop Services - Driveshaft #3 Run Driveshaft On Lathe Detected Bad Tubing	1	75.00	75.00
Industrial Machine Shop Services - Driveshaft #3 Replace Tube On Driveshaft & Re-Weld Yokes	2	225.00	450.00
Industrial Machine Shop Services - Driveshaft#3 Replace U-Joint From Driveshaft	1	75.00	75.00
4352324RX Turbocharger	1	3,480.00	3,480.00
4034315RX VGT Actuator	1	1,512.00	1,512.00
4955518 EGR Cooler	1	1,029.00	1,029.00
5473207RX EGR Valve	1	854.00	854.00
1229P4800 Snap Ring	1	8.00	8.00
3107K1181 Shift Collar	1	571.20	571.20
3892T5662 Input Low Gear	1	1,068.60	1,068.60
Thank you for your business.		<b>Subtotal</b>	
		<b>Sales Tax (8.25%)</b>	
		<b>Total</b>	

Phone #
9567230860

E-mail
CervantesTruckCenter@yahoo.com



Cervantes Truck Center, Inc.  
 5502 State Hwy 359  
 Laredo, TX 78043  
 PH (956) 723-0860

# Estimate

Date	Estimate #
8/18/2022	2022-0905

Name / Address
Webb County Attn: Business Office 1110 Washington Street, Ste #203 Laredo, Tx 78040

			Project
Description	Qty	Rate	Total
3892R5660 Gear	1	1,274.00	1,274.00
RWS5X1326 O-Ring Kit	1	35.00	35.00
100494 National Seal	3	38.50	115.50
80W90GAL Gallon Gear Lube	3	25.19	75.57
90-53-21 Center Bolt Stub Shaft	1	253.00	253.00
90-3-41X Slip Yoke	1	335.00	335.00
SPL100-1X Spicer U-Joint Old #SPL90X	3	125.00	375.00
90-70-28X Bearing & Strap Kit	1	17.00	17.00
90-4-341-1X End Yoke	1	485.00	485.00
RT 3 1/2" Regular .083 Driveline Tubing	2.5	20.00	50.00
212142-1X Center Bearing	1	120.50	120.50
90-70-28X Bearing & Strap Kit	4	17.00	68.00
Shipping & Handling (Engine & Transfer Case)	1	400.00	400.00
Shop Supplies	1	16.00	16.00
2010 Ford F750 Unit #58-04 Mileage: 056029 LIC # 111-6741 VIN # 3FRXW7FH7AV274777			
Thank you for your business.		<b>Subtotal</b>	\$19,072.37
		<b>Sales Tax (8.25%)</b>	\$0.00
		<b>Total</b>	\$19,072.37

Phone #
9567230860

E-mail
CervantesTruckCenter@yahoo.com