



## Webb County Constable Pct. 2

OFFENSE   
  INCIDENT   
  OTHER

1. <input type="checkbox"/> Victim's Name <input checked="" type="checkbox"/> Business Name <input type="checkbox"/> Complainant's Name <b>Constable Pct. 2</b>				2. Case Number:		3. Burglary Report (ONLY) <input type="checkbox"/> Bldg DT <input type="checkbox"/> Non-Res. DT <input type="checkbox"/> Bldg NT <input type="checkbox"/> Non-Res. NT		4. Reported by: <input type="checkbox"/> Phone <input type="checkbox"/> Officer <input type="checkbox"/> In Person <input type="checkbox"/> Letter			
5. Offense or Incident: <b>Unit 15-28 Engine Failure</b>				6. S.S.N.:		7. Type of Property: <input type="checkbox"/> LOST <input type="checkbox"/> STOLEN <input type="checkbox"/> REC'VD		8. Value of Property:	9. Value of Recovered Property		
10. <input type="checkbox"/> Victim's Address <input checked="" type="checkbox"/> Business Address <input type="checkbox"/> Complainant's Address <b>901 S Milmo Laredo, TX 78046</b>				11. Telephone #: <b>956-523-4780</b>		A. Currency, Notes, etc.					
12. Person Reporting and Address <b>Chief Deputy Ramiro Martinez, #0653</b>				13. Telephone #: <b>956-523-4780</b>		C. Clothing and Furs					
14. OCCURRED On or Btwn				15. REPORTED And				E. Office Equipment			
Month	Day	Year	Day Wk	Time	Month	Day	Year	Time			
05	21	2015	Thursday	7:45 am	05	21	2015	7:45 am			
16. Place of Occurrence <input type="checkbox"/> Inside <input checked="" type="checkbox"/> Outside				17. Type of Premises <input type="checkbox"/> Building <input checked="" type="checkbox"/> Motor Vehicle <input type="checkbox"/> Residence <input type="checkbox"/> Other				H. Household Goods			
18. Victim's Occupation				Race	Sex	Age	19. Person who discovered Crime or Incident <b>Chief Deputy Ramiro Martinez</b>				
20. Trademark or Unusual Event				21. Address of Number 19 <b>Same as #10</b>				J. Tools			
22. Photographs taken? <input type="checkbox"/> Crime Scene <input type="checkbox"/> Evidence <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Victim <input type="checkbox"/> Other				K. Miscellaneous <input type="checkbox"/> For other Authority		L. Auto Recovered <input type="checkbox"/> For other Authority					
23. VEHICLE <input type="checkbox"/> Stolen <input type="checkbox"/> Used by Offenders		24. COLOR	25. YEAR	26. MAKE	27. LICENSE NO.	28. STATE	29. BODY STYLE	30. VIN NUMBER	31. STORED AT		
32. (Specify) <input type="checkbox"/> TOOLS USED		33. WEAPON USED <input type="checkbox"/> Revolver <input type="checkbox"/> Shotgun <input type="checkbox"/> Rifle <input type="checkbox"/> Automatic				Knife (Describe)		Other			
Name and Description of Offender, Missing Person, Runaway, Etc. (List suspects in the Narrative)							Will Complainant Prosecute? <input type="checkbox"/> Yes <input type="checkbox"/> No S.S.N.    Arrested?				
34A. Last Name	First Name	MI	Address								
34B. Color	Sex	D.O.B.	Height	Weight	HAIR	Eyes	Complexion	Other (Scars, Tattoos, and Clothing, Etc.)			
35A. Last Name	First Name	MI	Address				S.S.N.		Arrested?		
35B. Color	Sex	D.O.B.	Height	Weight	Hair	Eyes	Complexion	Other (Scars, Tattoos, Clothing, Etc.)			
36. Evidence <input type="checkbox"/> None <input type="checkbox"/> Personal Belongings <input type="checkbox"/> Tools <input type="checkbox"/> Narcotics <input type="checkbox"/> Other			Description of Physical Evidence Obtained								
37. Witness Last Name		First Name	MI	Address			Residence Phone		Business Phone		

38. Article (Name Only) See No. 7	Quality	Value	Description (Include serial numbers where possible)		
39. Details as reported by the Victim, Person Reporting, and /or the Initial Investigation Officer:			Time Arrived At Scene	<input type="checkbox"/> AM <input type="checkbox"/> PM	
<p> <u>On May 21, 2015 at approximately 7:45 am, I Chief Deputy Ramiro Martinez, #0653 was commuting from my home to Constable Pct. 2 office at 901 S Milmo (corner of Zapata Hwy and Jaime Zapata Memorial Hwy), in my assigned unit 15-28. I was traveling North on US 83 (Zapata Hwy) and turned to the right on Ligarde St, since it had rained the previous night and continued to rain the morning of May 21, there was a puddle of water at the intersection of US 83 and Ligarde, another vehicle in front of me made the turn onto Ligarde and went through the puddle, so I also made the turn and proceeded to go through the puddle. After going through the water puddle my unit stalled, I attempted to turn it on again but it would only make a clicking sound. At or about 7:50 am Deputy Armando Rodriguez in a Tahoe unit 15-26 drove up behind me and pushed my unit into our parking lot. Around 8:35 pm I attempted to start the unit, the engine failed to start. On May 22 PO # 15-0005262 was issued to JR Martinez Auto South to tow the unit to Road and Bridge so it could be checked by the motor pool department. On May 27 motor pool reported that the engine had locked up and needed to be replaced.</u> </p>					
40. STATUS OF THE CASE: <input type="checkbox"/> REFERRED TO ARRESTED <input type="checkbox"/> ISSUE CITATION <input type="checkbox"/> CLEAR BY DETENTION <input type="checkbox"/> ACTIVE <input type="checkbox"/> INACTIVE <input type="checkbox"/> CLOSED <input type="checkbox"/> CLEARED BY ARREST <input type="checkbox"/> UNFOUNDED			41. DATE <b>5/28/2015</b>	42. Investigating Officer <b>Chief Deputy Ramiro Martinez</b>	43. Badge 0653
			44. DATE <b>5/28/2015</b>	45. Approving Supervisor <b>Constable Miguel Villarreal</b>	0661