

COUNTY OF WEBB

PRECINCT 1, 2, 3, & 4

1. **Condition of each road, culvert, and bridge in the precinct and the primary cause of any road, culvert or bridge degradation:**

**Webb County maintains approximately 335 miles of county roads. Only 55 are paved. Continued maintenance is required including the installation of flexible base materials due to degradation and damages from heavy truck traffic.**

2. **Amount of money necessary for maintenance of precinct roads during the next fiscal year:**

**\$350,000**


3. **Number of traffic control devices in the precincts defaced or torn down: 25**

4. **Any new road that should be opened in the precincts: NONE**


5. **Any bridges, culverts or other improvements necessary to place the precinct roads in good condition, and the probable costs of improvements:**

1. Welch Road culvert – Estimated cost \$100,000
2. Espejo Gates bridges (2) – Estimated cost \$100,000 each.
3. Nicholson rd. El Gato bypass bridge – Estimated cost \$100,000

Submitted by and undersigned on this 2 day of June, 2020.



Jose Luis Neira  
Road & Bridge Administrator



Tano E. Tijerina, Webb County Judge

## Webb County Road Conditions Report

ROAD NAME	LENGTH	CULVERTS	CONCRETE		DESIGN	SURFACE	CATTLE		ROAD CONDITIONS
			LOW WATER	CROSSING			GUARDS	LANES	
Espejo Gates Rd	13.17	26			2	32		2	Fair
Pico Rd	1.183	4			2	32	1	2	Poor
Pico Rd	0.062				2	32	1	2	Poor
Pico Rd	0.3				2	32		2	Poor
Pico Rd	0.42				2	51		2	Poor
Del Mar	0.366	0			2	51		2	Fair
Del Mar	3.428	1			2	51		2	Fair
Wormser Rd	8.082	9			0	32		2	Poor
Wormser Rd	0.34	0			2	32		2	Poor
Wormser Rd	2.302	0			0	32		2	Poor
Mangana Hein Rd	0.094	20			2	51	3	2	Fair
Mangana Hein Rd	2.091				2	51		2	Fair
Mangana Hein Rd	2.854				2	32		2	Fair
Mangana Hein Rd	4.151				2	51		2	Fair
Mangana Hein Rd	3.554				2	51		2	Fair
Pescadito Rd	1.118	1			2	32		2	Poor
Rubio Rd	2.128	4			2	32	2	2	Poor
Espejo Molina Rd	1.713	6			2	51		2	Fair
Espejo Molina Rd	2.095				2	51		2	Fair
Eagle Pass Rd	29.751	80			2	32	1	2	Fair
Chapote Mesas Rd	8.21	6			2	32	5	2	Poor
Las Tiendas Rd	9.926	7			2	32	7	2	Poor
San Juan Rd	2.461	1			2	32		2	Poor
Jefferies Rd	10.701	4			2	32	1	2	Fair
Galvan Rd	9.879	1			2	32	4	2	Fair
Jordan Rd	5.221	1			2	32	5	2	Poor
Jordan Rd	0.018				2	32		2	Poor
CR 1001	0.181				2	51		2	N/A
CR 1002	0.001				2	32		2	N/A
CR 1002	0.186				2	32		2	N/A
CR 1003	0.062				2	32		2	N/A
Jennings Rd	1.524	16			2	51		2	Fair
Jennings Rd	9.066				2	51		2	Fair
Jennings Rd	3.152				2	51		2	Fair
Vaquillas Rd	0.038	4			2	32	3	2	Fair
Vaquillas Rd	9.497				2	32		2	Fair
Vaquillas Rd	2.744				2	32		2	Fair

**KEY:**

Design:

Surface Type:

1 = One Way

10 = Natural

51 = Paved

2 = Two Way

32 = All Weather

61 = Concrete

3 = Blvd.

## Webb County Road Conditions Report

ROAD NAME	LENGTH	CULVERTS	CONCRETE		DESIGN	SURFACE	CATTLE		ROAD CONDITIONS
			LOW WATER CROSSING				GUARDS	LANES	
Magnolia Rd	0.472	1			2	32	1	2	Poor
Welhousen Rd	18.23	16			2	32	13	2	Poor
Welhousen Rd	0.292				2	51		2	Poor
Welhousen Rd	0.062				2	51		2	Poor
Carolina Rd	0.003	1			2	32	5	2	Poor
Carolina Rd	6.464				2	32		2	Poor
JC Perez Rd	1				2	32		2	Poor
JC Perez Rd	0.003				2	32		2	Poor
Moreno Rd	0.087				2	32		2	Poor
Moreno Rd	0.505				2	32		2	Poor
Moreno Rd	0.001				2	32		2	Poor
Jim Neal Rd	0.309				2	32		2	Good
Mackin Rd	0.307				2	32		2	Good
Bonita Rd	0.106				2	32		2	Good
Bonita Rd	0.217				2	32		2	Good
Laurel Rd	0.001				2	51		2	Good
Laurel Rd	0.233				2	51		2	Good
Laurel Rd	0.049				2	32		2	Good
Ramona Rd	0.172				2	32		2	Good
Ramona Rd	0.001				2	51		2	Good
Ramona Rd	0.222				2	51		2	Fair
Molina Rd	0.281				2	51		2	Fair
Nicholson Rd	15.2	12			2	32	5	2	Fair
Nicholson Rd	0.049				2	32		2	Fair
Lincoln Rd	3.809				2	32		2	Fair
Lincoln Rd	0.004				2	32		2	Fair
Callaghan Rd	18.035	22			2	32	2	2	Fair
Becerra Rd	2.01				2	32		2	Poor
Becerra Rd	0.001				2	32		2	Poor
Raices Rd	6.618	6			2	32	2	2	Fair
Alamo Rd	5.537	1			2	32	1	2	Fair
Martinena Rd	7.613	16			2	51		2	Fair
Martinena Rd	0.032				2	51		2	Fair
Zamora Rd	3.105	7			2	32	2	2	fair
Zamora Rd	0.01				2	32		2	Fair
Cerrito Prieto Rd	0.029				2	32		2	N/A
Webb Rd	2.688	1			2	32		2	Poor

**KEY:** Design: Surface Type:

1 = One Way

10 = Natural 51 = Paved

2 = Two Way

32 = All Weather 61 = Concrete

3 = Blvd.

**Webb County  
Road Conditions Report**

ROAD NAME	LENGTH	CULVERTS	CONCRETE		CATTLE		ROAD CONDITIONS
			LOW WATER CROSSING	DESIGN	SURFACE	GUARDS LANES	
Pintas Adami South	2.778			2	32	2	Fair
Pintas Adami South	0.011			2	32	2	Fair
Pintas Adami South	6.797			2	32	2	Fair
Pintas Adami South	0.03			2	32	2	Fair
Withers	3.165			2	32	2	Poor
Withers	2.453			2	10	2	Poor
Mills Bennet Rd	2.165			2	32	2	Poor
Superior Rd	1.696			2	32	2	Poor
Superior Rd	0.005			2	32	2	Poor
San Pablo Rd	3.135			2	32	2	Poor
San Pablo Rd	0.013			2	32	2	Poor
San Nino Rd	0.012			2	32	2	Poor
San Nino Rd	2.466			2	32	2	Poor
United Gas Rd	2.279	no longer a county maintained r		2	32	2	N/A
CR 1038	1.29			2	51	2	N/A
Foster Rd	0.352			2	32	2	Good
Despin Rd	0.348			2	32	2	Good
Garcia Rd	0.357			2	51	2	Good
Garcia Rd	0.086			2	32	2	Good
CR 1044	0.001			2	32	2	N/A
CR 1044	0.112			2	32	2	N/A
Panther Ave	0.179			2	51	2	Good
Panther Ave	0.002			2	51	2	Good
Panther Ave	0.293			2	51	2	Good
Panther Ave	0.038			2	32	2	Good
Linder Ave	0.152			2	51	2	Good
Linder Ave	0.005			2	51	2	Good
Behlen Ave	0.001			2	51	2	Good
Behlen Ave	0.397			2	51	2	Good
Garcia St	0.334			2	32	2	Good
Garcia St	0.193			2	32	2	Good
Webb Ave	0.17			2	32	2	Good
Zapata	0.157			2	32	2	Good
Ojuelos Ave	0.154			2	32	2	Good
Dr. JW Edgar Rd	0.143			2	32	2	Good
Dr. JW Edgar Rd	0.369			2	51	2	Good
First St	0.414	1		2	51	2	Good

**KEY:**

Design:

Surface Type:

1 = One Way

10 = Natural

51 = Paved

2 = Two Way

32 = All Weather

61 = Concrete

3 = Blvd.

**Webb County  
Road Conditions Report**

ROAD NAME	LENGTH	CULVERTS	CONCRETE		CATTLE		ROAD CONDITIONS
			LOW WATER CROSSING	DESIGN	SURFACE	GUARDS LANES	
First St	0.007			2	51		2 Good
First St	0.038			2	32		2 Good
First St	0.062			2	32		2 Good
2nd St	0.243			2	32		2 Good
3rd St	0.18			2	51		2 Good
4th St	0.063			2	32		2 Good
CR 1058	0.067			2	32		2 N/A
CR 1059	0.049			2	32		2 N/A
Fifth St	0.064			2	51		2 Fair
Fifth St	0.058			2	32		2 Fair
Fifth St	0.121			2	51		2 Fair
Fifth St	0.062			2	32		2 Fair
Fifth St	0.002			2	32		2 Fair
Sixth St	0.114			2	51		2 Fair
Sixth St	0.037			2	32		2 Fair
Sixth St	0.206			2	51		2 Fair
Sixth St	0.005			2	32		2 Fair
Sixth St	0.036			2	51		2 Fair
7th St	0.239			2	51		2 Fair
7th St	0.001			2	32		2 Fair
7th St	0.057			2	32		2 Fair
7th St	0.005			2	32		2 Fair
Avenue B	0.33			2	51		2 Fair
Avenue B	0.001			2	51		2 Fair
Avenue C	0.056			2	32		2 Fair
Avenue C	0.339			2	51		2 Fair
Avenue D	0.129			2	32		2 Fair
Avenue E	0.339			2	51		2 Fair
Avenue E	0.188			2	32		2 Fair
Avenue F	0.445			2	32		2 Fair
Avenue G	0.002			2	51		2 Fair
Avenue G	0.905			2	51		2 Fair
2nd St	0.203			2	32		2 Fair
4th St	0.298			2	51		2 Fair
4th St	0.001			2	51		2 Fair
5th St	0.299			2	32		2 Fair
6th St	0.358			2	51		2 Fair

**KEY:**

Design:	Surface Type:	1 = One Way	10 = Natural	51 = Paved
		2 = Two Way	32 = All Weather	61 = Concrete
		3 = Blvd.		

**Webb County  
Road Conditions Report**

ROAD NAME	LENGTH	CULVERTS	CONCRETE		CATTLE		ROAD CONDITIONS
			LOW WATER CROSSING	DESIGN	SURFACE	GUARDS LANES	
6th St	0.003			2	51	2	Fair
7th St	0.18			2	32	2	Fair
8th	0.3			2	51	2	Fair
7th St	0.062			2	32	2	Fair
9th St	0.06			2	32	2	Fair
12th St	0.189			2	51	2	Fair
12th St	0.049			2	51	2	Fair
12th St	0.001			2	51	2	Fair
12th St	0.12			2	32	2	Fair
Avenue D	0.244			2	32	2	Fair
CR 1084	0.259			2	32	2	N/A
15th St	0.001			2	32	2	Fair
15th St	0.202			2	32	2	Fair
Linder Ave	0.288			2	32	2	Fair
Linder Ave	0.002			2	32	2	Fair
Theisel	0.247	1		2	32	2	Poor
Theisel	0.111			2	32	2	Poor
Phelps	0.09			2	32	2	Poor
Phelps	0.146			2	51	2	Poor
Phelps	0.335			2	32	2	Fair
Penitas Rd	2.028			2	51	2	Fair
Dawson Ln	0.448			2	32	2	Fair
Nietos St	0.096			2	32	2	Fair
Milagro Rd	0.377			2	32	2	Fair
Milagro Rd	0.129			2	32	2	Fair
Maria Elena	0.259			2	32	2	Fair
Maria Elena	0.257			2	32	2	Fair
Main St	0.817			2	32	2	Fair
CR 1110	0.544			2	32	2	N/A
Los Botines Ln	0.516			2	32	2	Fair
Well Ln	1.209			2	32	2	Fair
Well Ln	0.002			2	32	2	Fair
Garza Jones Ln	1.002			2	32	2	Fair
Pearson Moss Ln	0.889			2	32	2	Fair
Pearson Moss Ln	0.001			2	32	2	Fair
Don Castor	0.503			2	32	2	Fair
Wilson Rd	0.029			2	51	2	Fair

**KEY:**

Design:

Surface Type:

1 = One Way

10 = Natural

51 = Paved

2 = Two Way

32 = All Weather

61 = Concrete

3 = Blvd.

**Webb County  
Road Conditions Report**

ROAD NAME	LENGTH	CULVERTS	CONCRETE		CATTLE		ROAD CONDITIONS
			LOW WATER CROSSING	DESIGN	SURFACE	GUARDS LANES	
Wilson Rd	0.097			2	51	2	Fair
Wilson Rd	0.123			2	32	2	Fair
Colorado	1.874			2	32	2	Poor
Don Antonio	2.959			2	32	2	Poor
Camino Del Este	2.365			2	32	2	Poor
Norte	0.712			2	32	2	Poor
R.R. 7150	0.014			2	32	2	Fair
R.R. 7150	2.774			2	32	2	Fair
R.R. 7150	0.009			2	32	2	Fair
R.R. 7150	1.907			2	32	2	Fair
CR1127	0.005			2	32	2	N/A
CR 1127	1.269			2	32	2	N/A
San Luis	0.003			2	32	2	Poor
San Luis	0.398			2	32	2	Poor
Monte Vista	0.003			2	32	2	Poor
Monte Vista	0.629			2	32	2	Poor
Granada	0.244			2	32	2	Poor
Durango	1.38			2	32	2	Poor
Trinidad	0.214			2	32	2	Poor
Cortez	0.166			2	32	2	Poor
Cortez	0.516			2	32	2	Poor
Sur	1.214			2	32	2	Poor
CR 1141	1.385			2	32	2	N/A
Los Lomas Rd	0.265			2	32	2	Fair
CR 1143	1.922			2	32	2	N/A
CR 1144	1.052			2	32	2	N/A
CR 1145	0.947			2	32	2	N/A
CR 1146	0.894			2	32	2	N/A
CR 1147	0.001			2	32	2	N/A
CR 1147	1.15			2	32	2	N/A
CR 1148	1.156			2	32	2	N/A
Silver Rd	0.165			2	32	2	Poor
Sulfur Mine Rd	0.324			2	32	2	Poor
CR 1202	0.344			2	32	2	?
Jones Rd	0.094			2	32	2	Good
Avenue A	0.229			2	32	2	Good
Avenue A	0.097			2	32	2	Good

**KEY:**

Design:

Surface Type:

1 = One Way

10 = Natural

51 = Paved

2 = Two Way

32 = All Weather

61 = Concrete

3 = Blvd.

**Webb County  
Road Conditions Report**

ROAD NAME	LENGTH	CULVERTS	CONCRETE		CATTLE		ROAD CONDITIONS
			LOW WATER CROSSING	DESIGN	SURFACE	GUARDS LANES	
Avenue A	0.074			2	51	2	Good
Avenue C	0.133			2	32	2	Good
Eleventh St	0.056			2	32	2	Good
Eleventh St	0.124			2	51	2	Good
Thirteenth St	0.072			2	32	2	Good
Thirteenth St	0.119			2	51	2	Good
Thirteenth St	0.049			2	32	2	Good
Sixteenth	0.116			2	32	2	Good
Webb Ave	0.197			2	32	2	Good
Zapata Ave	0.152			2	32	2	Good
CR 1213	0.044			2	32	2	N/A
Botello Rd	1.846			2	32	2	N/A
Saenz Rd	0.187			2	32	2	Fair
Ibarra Rd	0.378			2	32	2	Good
Miers Rd	0.475			2	32	2	Fair
Alvarado Rd	0.476			2	32	2	Fair
Gomez Ave	0.478			2	32	2	Fair
Mendoza Ave	0.438			2	32	2	Fair
Lampazos	0.465			2	32	2	N/A
Ozuna Ave	0.465			2	32	2	Fair
Tanquecitos Rd	0.681			2	32	2	Good
Riata Rd	0.286			2	32	2	Good
Riata Rd	0.006			2	32	2	Good
El Rocio Rd	0.418			2	32	2	Good
Arco Iris Rd	0.379			2	32	2	Good
El Lucero	0.399			2	32	2	Good
Los Altos	0.671			2	32	2	Good
Amanecer Rd	0.365			2	32	2	Good
Enlace Rd	0.973	1		2	32	2	Good
Estrella Rd	0.144	0		2	32	2	Good
Emiliano Rd	0.003	1		2	32	2	Good
Emiliano Rd	0.73	1		2	32	2	Good
Escandon Rd	0.296	0		2	32	2	Good
Amy Rd	0.298	0		2	32	2	Good
Pinzon Rd	0.726	0		2	32	2	Good
Barrera Rd	0.371	0		2	32	2	Good
Adelita Rd	0.119	0		2	32	2	Good

**KEY:**

Design:

Surface Type:

1 = One Way

10 = Natural

51 = Paved

2 = Two Way

32 = All Weather

61 = Concrete

3 = Blvd.



**Webb County  
Road Conditions Report**

ROAD NAME	LENGTH	CULVERTS	CONCRETE		DESIGN	SURFACE	CATTLE		ROAD CONDITIONS
			LOW WATER CROSSING				GUARDS	LANES	
Nacogdoches Rd	0.139	0			2	32		2	Poor
Gutierrez Rd	0.117	0			2	32		2	Good
Kay Bailey Rd	0.083	0			2	32		2	Poor
Welch Rd	0.67	1			2	32		2	Poor
Gore Rd	0.065	0			2	32		2	Poor
Old Milwaukee	0.4	0			2	32		2	Good
Old Milwaukee	0.091	0			2	32		2	Good
Harrison Rd	0.034	0			2	32		2	Good
CR 1248	0.062				2	32		2	N/A
Mercury Mine Rd	0.332	0			2	32		2	Poor

**KEY:**

**Design:**

**Surface Type:**

1 = One Way

10 = Natural      51 = Paved

2 = Two Way

32 = All Weather      61 = Concrete

3 = Blvd.